

# RC Škoda Octavia 1



1:24 scale, fully 3D printed on FDM




More models at:

**[www.3drcmodels.com](http://www.3drcmodels.com)**


# 1. Chasses



1



2




3




You need 2x 4mm long ~1.1mm thin wire.  
Best are paper clips.


4




6



5





7



 2x M1x5




You can choose motor RPM. For faster driving use 500 - 750 RPM. I have used 300 RPM.



2x


10

*i*  
Bearings 6x3x2 has to fit very tight on axle. If axle is too big, you can use sandpaper.




4x M1x4

11




12



 2x M1.2x4


14

 4x M1x3




13

 4x M1x3



15


 4x M1.2x4




Bearings 6x2x3 should fit quite firm to axle. If necessary, you can again use sandpaper.



Steering ping have to be very tight so it won't slip during steering.



16




2x M1x5

17

18




1x M1x3




Battery

Receiver




ESC

19



**Great job!**


The chassis is done!  
Now let's do the body.





1

 4x M1x5




3



2

 2x M1x4



4


 4x M1x4

5



7


2x M1x4




6



8



 4x M1x4



9



11



10



12

13



15



14



**Great job!**

We are done...

For more models, visit:

**[www.3drcmodels.com](http://www.3drcmodels.com)**